



Bi- annual inspection form for PCB encapsulated areas

Date: 04/11/2011

Building: Gage Hall

Condition of encapsulated area: Good

Comments: Recoated all surfaces in July 2010 based upon one above detection yet lower than action level wipe sample

Recommendations: None at this time, re-inspect in Oct/Nov 2011

Date: 04/11/2011

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in Oct/Nov 2011

Date: 04/11/2011

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in Oct/Nov 2011



Bi- annual inspection form for PCB encapsulated areas

Date 04/11/2011

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Due to construction of high temp hot water lines, walls outside of actual vault room were re-coated in July 2010.

Recommendations: None at this time, re-inspect in Oct/Nov 2011

Date: 04/11/2011

Building: Parker Theater

Condition of encapsulated area: Good

Blacktop integrity Southeast corner Driveway: Good

Comments: Due to slight bubble in one small (less than 4 sq inches) area on floor of transformer pit, it was patched and re-coated in July 2010. In addition, one PCB wipe sample was above detection limit (yet below clean-up criteria), that area was re-coated in July 2010.

Recommendations: None at this time, re-inspect in Oct/Nov 2011

Inspections by _____Michael Malloy_____