



Bi- annual inspection form for PCB encapsulated areas

Date: 10/02/09

Building: Gage Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2010

Date: 10/02/09

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2010

Date: 10/02/09

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: Plywood fixed area looks good fixed from previous inspection

Recommendations: None at this time, re-inspect in April 2010



Bi- annual inspection form for PCB encapsulated areas

Date 10/02/09

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Slight staining on encapsulant outside of enclosed room, PCB wipe sample in May taken, no PCB detected, probable staining on ceiling from recent contractor activity for high temp hot water lines installation and hook up.

Recommendations: None at this time, re-inspect in April 2010

Date: 10/02/09

Building: Parker Theater

Condition of encapsulated area: Good

Blacktop integrity Southeast corner Driveway: Good

Comments: None at this time, re-inspect in April 2010, previous 04/09 comments of staining was attributed to duct tape glue residue upon further investigation.

Recommendations: None at this time, re-inspect in April 2010

Inspections by _____ Michael Malloy _____