



Bi- annual inspection form for PCB encapsulated areas

Date: 10/15/08

Building: Gage Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2009

Date: 10/15/08

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2009


Date: 10/15/08

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2009



Bi- annual inspection form for PCB encapsulated areas

Date 10/15/08

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Encapsulated areas have materials stored against them which could damage the encapsulant, New Encapsulant applied to new HTHW line penetration under supervision of Clean Harbors. Will re-inspect in April 2009

Recommendations:

- 1) Require that encapsulated walls remain free of any item (leaning against the wall), as storage against these walls may damage the encapsulant

Date: 10/15/08

Building: Parker Theater

Condition of encapsulated area: Good

Comments: None at this time, re-inspect in April 2009

Recommendations:

Inspections by _____ Michael Malloy _____