



Bi- annual inspection form for PCB encapsulated areas

Date: 04/12/10

Building: Gage Hall

Condition of encapsulated area: Good

Comments: One 2009 PCB wipe sample (still below clean-up criteria) was elevated from last sampling, will re-coat in July 2010

Recommendations: will re-coat July 2010, and re-inspect in October 2010

Date: 04/12/10

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2010

Date: 04/12/10

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2010



Bi- annual inspection form for PCB encapsulated areas

Date 04/12/10

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Noted some construction activity near an encapsulated wall, 2009 PCB wipe samples were OK, walls may need re-coat, will re-coat in July 2010.

Recommendations: Re-coat small section in July, re-inspect in October 2010

Date: 04/12/10

Building: Parker Theater

Condition of encapsulated area: Good

Blacktop integrity Southeast corner Driveway: Good

Comments: Slight bubble in one small (less than 4 sq inches) area on floor of transformer pit, will patch and re-coat in July 2010. One PCB wipe sample was above detection limit (yet below clean-up criteria), will recoat small section in July 2010. 2009 wipe samples were OK

Recommendations: Re-coat small areas in July, re-inspect in October 2010

Inspections by _____ Michael Malloy