



Bi- annual inspection form for PCB encapsulated areas

Date: 10/11/2011

Building: Gage Hall

Condition of encapsulated area: Good

Comments: Recoated all surfaces in July 2010

Recommendations: None at this time, re-inspect in April 2012

Date: 10/11/2011

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2012

Date: 10/11/2011

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2012



**Bi- annual inspection form for PCB
encapsulated areas**

Date 10/11/2011

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Due to construction of high temp hot water lines, walls outside of actual vault room were re-coated in July 2010.

Recommendations: None at this time, re-inspect in April 2012

Date: 10/11/2011


Building: Parker Theater

Condition of encapsulated area: Good

Blacktop integrity Southeast corner Driveway: Good

Comments: Small areas were re-coated in July 2010.

Recommendations: None at this time, re-inspect in April 2012

Inspections by _____ Michael Malloy  _____ 10/11/11 _____