



## Bi- annual inspection form for PCB encapsulated areas

**Date:** 04/08/2013

**Building:** Gage Hall

**Condition of encapsulated area:** Good

**Comments:** Recoated all surfaces in July 2010

**Recommendations:** None at this time, re-inspect in October 2013

**Date:** 04/08/2013

**Building:** Bliss Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2013

**Date:** 04/08/2013

**Building:** Scudder Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2013



## Bi- annual inspection form for PCB encapsulated areas

**Date:** 04/08/2013

**Building:** Coykendall Science Building

**Condition of encapsulated area:** Good

**Comments:** Due to construction of high temp hot water lines, walls outside of actual vault room were re-coated in July 2010.

**Recommendations:** None at this time, re-inspect in October 2013

**Date:** 04/08/2013

**Building:** Parker Theater

**Condition of encapsulated area:** Good

**Comments:** Small areas were re-coated in July 2010.

**Blacktop integrity Southeast corner Driveway:** Good

**Recommendations:** None at this time, re-inspect in October 2013

Inspections by \_\_\_\_\_Michael Malloy\_\_\_\_\_04/08/2013\_\_\_\_\_