

Bi- annual inspection form for PCB encapsulated areas

Date: 10/29/2013

Building: Gage Hall

Condition of encapsulated area: Good

Comments: Recoated all surfaces in July 2010

Recommendations: None at this time, re-inspect in April 2014

Date: 10/29/2013

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2014

Date: 10/29/2013

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2014



Bi- annual inspection form for PCB encapsulated areas

Date: 10/29/2013 **Building: Coykendall Science Building** Condition of encapsulated area: Good Comments: Due to construction of high temp hot water lines, walls outside of actual vault room were re-coated in July 2010. Recommendations: None at this time, re-inspect in April 2014 Date: 04/08/2013 **Building: Parker Theater** Condition of encapsulated area: Slight discoloration on floor Comments: Small areas were re-coated in July 2010. Blacktop integrity Southeast corner Driveway: Good Recommendations: Re-coat walls and floor in near future and re-inspect in April 2014 Inspections by _____