



## Bi- annual inspection form for PCB encapsulated areas

**Date:** 04/30/2014

**Building:** Gage Hall

**Condition of encapsulated area:** Good

**Comments:** Recoated all surfaces in July 2010

**Recommendations:** None at this time, re-inspect in October 2014

**Date:** 04/30/2014

**Building:** Bliss Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2014

**Date:** 04/30/2014

**Building:** Scudder Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2014



**Bi- annual inspection form for PCB  
encapsulated areas**

**Date: 04/30/2014**

**Building: Coykendall Science Building**

**Condition of encapsulated area: Good**

**Comments:** Due to construction of high temp hot water lines, walls outside of actual vault room were re-coated in July 2010.

**Recommendations:** None at this time, re-inspect in October 2014

**Date: 04/30/2014**

**Building: Parker Theater**

**Condition of encapsulated area: Slight discoloration on floor**

**Comments:** Small areas were re-coated in July 2010.

**Blacktop integrity Southeast corner Driveway: Good**

**Recommendations:** Re-coat walls and floor in near future and re-inspect in October 2014

Inspections by Michael Malloy 04/30/2014

A handwritten signature in black ink, appearing to be 'Michael Malloy', written over a horizontal line.