



Bi- annual inspection form for PCB
encapsulated areas

Date: 10/07/2014

Building: Gage Hall

Condition of encapsulated area: Good

Comments: Recoated all surfaces in July 2010

Recommendations: None at this time, re-inspect in April 2015

Date: 10/07/2014

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2015

Date: 10/07/2014

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2015



**Bi- annual inspection form for PCB
encapsulated areas**

Date: 10/07/2014

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Due to construction of high temp hot water lines, walls outside of actual vault room were re-coated in July 2010.

Recommendations: None at this time, re-inspect in April 2015

Date: 10/07/2-14

Building: Parker Theater

Condition of encapsulated area: New

Comments: Entire Vault was re-encapsulated in September 2014.

Blacktop integrity Southeast corner Driveway: Good

Recommendations: Verify coating with air samples in Fall of 2014 re-inspect in April 2015

Inspections by _____ Michael Malloy  _____ 10/07/2014