



**Bi- annual inspection form for PCB
encapsulated areas**

Date: 04/05/2012

Building: Gage Hall

Condition of encapsulated area: Good

Comments: Recoated all surfaces in July 2010

Recommendations: None at this time, re-inspect in October 2012

Date: 04/05/2012

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2012

Date: 04/05/2012

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2012



**Bi- annual inspection form for PCB
encapsulated areas**

Date: 04/05/2012

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Due to construction of high temp hot water lines, walls outside of actual vault room were re-coated in July 2010.

Recommendations: None at this time, re-inspect in October 2012

Date: 04/05/2012

Building: Parker Theater

Condition of encapsulated area: Good

Comments: Small areas were re-coated in July 2010.

Blacktop integrity Southeast corner Driveway: Good

Recommendations: None at this time, re-inspect in October 2012

Inspections by Michael Malloy 04/05/2012

A handwritten signature in black ink, appearing to be 'Michael Malloy', written over a horizontal line.