



## Bi- annual inspection form for PCB encapsulated areas

**Date:** 04/29/2016

**Building:** Gage Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in September 2016

**Date:** 04/29/2016

**Building:** Bliss Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in September 2016

**Date:** 04/29/2016

**Building:** Scudder Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in September 2016



**Bi- annual inspection form for PCB  
encapsulated areas**

**Date:** 04/29/2016

**Building:** Coykendall Science Building

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in September 2016

**Date:** 04/29/2016


**Building:** Parker Theater

**Condition of encapsulated area:** New

**Comments:** Entire Vault was re-encapsulated in September 2014.

**Blacktop integrity Southeast corner Driveway:** Good

**Recommendations:** None at this time, re-inspect in September 2016

Inspections by  \_\_\_\_\_ 05/05/2016  
Michael Malloy