



## Bi- annual inspection form for PCB encapsulated areas

**Date:** 09/21/2016

**Building:** Gage Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in April 2017

**Date:** 09/21/2016

**Building:** Bliss Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in April 2017

**Date:** 09/21/2016

**Building:** Scudder Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in April 2017



Bi- annual inspection form for PCB  
encapsulated areas

**Date:** 09/21/2016

**Building:** Coykendall Science Building

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in April 2017

**Date:** 09/21/2016

**Building:** Parker Theater


**Condition of encapsulated area:** New

**Comments:** Entire Vault was re-encapsulated in September 2014.

**Blacktop integrity Southeast corner Driveway:** Good

**Recommendations:** None at this time, re-inspect in April 2017

Inspections by \_\_\_\_\_ 09/21/2016

  
Michael Malloy