



## Bi- annual inspection form for PCB encapsulated areas

**Date:** 11/01/2017

**Building:** Gage Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect on or about April 2018

**Date:** 11/01/2017

**Building:** Bliss Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect on or about April 2018

**Date:** 11/01/2017

**Building:** Scudder Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect on or about April 2018



Bi- annual inspection form for PCB  
encapsulated areas

**Date:** 11/01/2017

**Building:** Coykendall Science Building

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect on or about April 2018


**Date:** 11/01/2017

**Building:** Parker Theater

**Condition of encapsulated area:** Good

**Blacktop integrity Southeast corner Driveway:** Good

**Recommendations:** None at this time, re-inspect on or about April 2018

Inspections by  11/01/2017  
Michael Malloy