

Bi-annual PCB Encapsulation Inspection

Building & Location:	Parker Theater – Electrical Room
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022

Building & Location:	Parker Theater – Vault
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022

Building & Location:	Scudder Hall
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022

Building & Location:	Coykendall Science Building - Vault
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022

Building & Location:	Coykendall Science Building – Electrical Room
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022



Building & Location:	Bliss Hall - Vault
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022

Building & Location:	Bliss Hall – Electrical Room
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022

Building & Location:	Gage Hall – Electrical Room
Condition of Encapsulated Area:	Good
Comments:	None
Recommendations:	None – Re-inspect April 2022

Date of Inspection:	10/13/2021
Inspected By Name:	Kyle Mungavin
Signature:	