



Bi- annual inspection form for PCB encapsulated areas

Date: 10/05/10

Building: Gage Hall

Condition of encapsulated area: Good (new)

Comments: applied new coating in July 2010 based upon previous inspection

Recommendations: None at this time , re-inspect in March/April 2011

Date: 10/05/10

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in March/April 2011

Date: 10/05/10

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in March/April 2011

Inspections by _____ Michael Malloy



Bi- annual inspection form for PCB encapsulated areas

Date 10/06/10

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: Noted some construction activity near an encapsulated wall from last inspection 2009 PCB wipe samples were OK, some walls were re-coated in July 2010.

Recommendations : None at this time, re-inspect in March/April 2011

Date: 10/06/10

Building: Parker Theater


Condition of encapsulated area: Good

Blacktop integrity Southeast corner Driveway: Good

Comments: Based upon last inspection some areas were re-coated in July 2010, 2009 wipe samples were OK

Recommendations: None at this time, re-inspect in March/April 2011

Inspections by _____ Michael Malloy _____

 10/14/10