



## Bi- annual inspection form for PCB encapsulated areas

**Date:** 04/14/2021

**Building:** Gage Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2021

**Date:** 04/14/2021

**Building:** Bliss Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2021

**Date:** 04/14/2021

**Building:** Scudder Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2021



**Bi- annual inspection form for PCB encapsulated areas**

**Date:** 04/14/2021

**Building:** Coykendall Science Building

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2021

**Date:** 04/14/2021

**Building:** Parker Theater

**Condition of encapsulated area:** Good

**Blacktop integrity Southeast corner Driveway:** Good

**Recommendations:** None at this time, re-inspect in October 2021

Inspections by \_\_\_\_\_

  
Michael Malloy

04/14/2021