



Bi- annual inspection form for PCB  
encapsulated areas

**Date:** 04/02/2020

**Building:** Gage Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2020

**Date:** 04/02/2020

**Building:** Bliss Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2020

**Date:** 04/02/2020

**Building:** Scudder Hall

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2020



Bi- annual inspection form for PCB  
encapsulated areas

**Date:** 04/02/2020

**Building:** Coykendall Science Building

**Condition of encapsulated area:** Good

**Comments:** None

**Recommendations:** None at this time, re-inspect in October 2020

**Date:** 04/02/2020

**Building:** Parker Theater

**Condition of encapsulated area:** Good

**Blacktop integrity Southeast corner Driveway:** Good

**Recommendations:** None at this time, re-inspect in October 2020

Inspections by  \_\_\_\_\_ 04/02/2020  
Michael Malloy