

## Bi-annual PCB Encapsulation Inspection

<b>Building &amp; Location:</b>	<b>Parker Theater – Electrical Room</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Building &amp; Location:</b>	<b>Parker Theater – Vault</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Building &amp; Location:</b>	<b>Scudder Hall</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Building &amp; Location:</b>	<b>Coykendall Science Building - Vault</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Building &amp; Location:</b>	<b>Coykendall Science Building – Electrical Room</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Building &amp; Location:</b>	<b>Bliss Hall - Vault</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Building &amp; Location:</b>	<b>Bliss Hall – Electrical Room</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Building &amp; Location:</b>	<b>Gage Hall – Electrical Room</b>
<b>Condition of Encapsulated Area:</b>	Good
<b>Comments:</b>	None
<b>Recommendations:</b>	None – Re-inspect October 2022

<b>Date of Inspection:</b>	<b>04/13/2022</b>
<b>Inspected By Name:</b>	<b>Kyle Mungavin</b>
<b>Signature:</b>	<i>Kyle Mungavin</i>