



Bi- annual inspection form for PCB
encapsulated areas

Date: 04/01/2019

Building: Gage Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2019

Date: 04/01/2019

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2019

Date: 04/01/2019

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2019



Bi- annual inspection form for PCB
encapsulated areas

Date: 04/01/2019

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in October 2019

Date: 04/01/2019

Building: Parker Theater

Condition of encapsulated area: Good

Blacktop integrity Southeast corner Driveway: Good

Recommendations: None at this time, re-inspect in October 2019

Inspections by


Michael Malloy

04/01/2019