



Bi- annual inspection form for PCB encapsulated areas

Date: 10/02/2019

Building: Gage Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2020

Date: 10/02/2019

Building: Bliss Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2020

Date: 10/02/2019

Building: Scudder Hall

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2020



Bi- annual inspection form for PCB
encapsulated areas

Date: 10/02/2019

Building: Coykendall Science Building

Condition of encapsulated area: Good

Comments: None

Recommendations: None at this time, re-inspect in April 2020

Date: 10/02/2019


Building: Parker Theater

Condition of encapsulated area: Good

Blacktop integrity Southeast corner Driveway: Good

Recommendations: None at this time, re-inspect in April 2020

Inspections by _____ 10/02/2019


Michael Malloy