



Building # 31 (SAB)
Smiley Art Building




STUDIO BASEMENT PLAN

Smiley Art Building




FIRST FLOOR PLAN

Smiley Art Building



2ND FLOOR PLAN

Smiley Art Building



11'6"

Pent House Floor Plan



Client: Clean Harbors of Kingston, Inc.
Sample I.D.: BLDG. 31A, SMILEY
Sample Type: Wipe

CHAS Lab #: 9201035-08N
Date Received: 01/04/92

Polychlorinated Biphenyls (PCBs)

Extraction Date: 01/04/92
Analysis Date: 01/04/92

Parameter	MDL	Concentration	Units
PCB - Aroclor 1016	0.3	ND	ug/100 sq cm
PCB - Aroclor 1221	0.3	ND	ug/100 sq cm
PCB - Aroclor 1232	0.3	ND	ug/100 sq cm
PCB - Aroclor 1242	0.3	ND	ug/100 sq cm
PCB - Aroclor 1248	0.3	ND	ug/100 sq cm
PCB - Aroclor 1254	0.3	ND	ug/100 sq cm
PCB - Aroclor 1260	0.3	0.4	ug/100 sq cm

Notes: ND = Below minimum detectable level (MDL)
Wipe Area: 400 sq cm

The sample was mixed with hexane for 5 minutes. The resulting extract was analyzed by GC/ECD following EPA Method 8080.



QUALITY CONTROL

REPORT OF ANALYSIS

CHAS LAB. NO. 9201035

The attached quality control data was generated during the analysis of these samples. The sample data has been corrected for analytes found in the blank (if any). Corrections were performed in accordance with the procedures as stated in the Clean Harbors Analytical Laboratory QA/QC Manual and pertinent SOP's, which are available for review. This data is submitted for informational purposes only.



Client: Clean Harbors of Kingston, Inc.

CHAS Lab #: 9201035

Polychlorinated Biphenyls (PCB's) Blank

Extraction Date: 01/04/92

Analysis Date: 01/04/92

Parameter	MDL	Concentration	Units
PCB - Aroclor 1016	0.3	ND	ug/100 sq cm
PCB - Aroclor 1221	0.3	ND	ug/100 sq cm
PCB - Aroclor 1232	0.3	ND	ug/100 sq cm
PCB - Aroclor 1242	0.3	ND	ug/100 sq cm
PCB - Aroclor 1248	0.3	ND	ug/100 sq cm
PCB - Aroclor 1254	0.3	ND	ug/100 sq cm
PCB - Aroclor 1260	0.3	ND	ug/100 sq cm

Note: ND - Below minimum detectable level (MDL)
Soil/solid sample results based on sample dry weight

The sample was mixed with hexane for 5 minutes. The resulting extract was analyzed by GC/ECD following EPA Method 8080.

CleanHarbors

Clean Harbors Analytical, 325 Wood Rd., Braintree, MA. 02184 CHAIN OF CUSTODY RECORD Sample Custodian - (617) 849-6070 Page 1 of 1

Client: Albany Project Name: SUN New Paltz College Subject/P.O. #: A8820 Date: _____

Report To: _____ Address: _____ Phone #: _____

Invoice To: _____ Address: _____

Date Samples Collected: 1/3 + 1/4/92 by: Loe lafante Date Samples Received: _____

Airbill/Bill of Lading? (N) NOTE: Samples received unpreserved will be preserved upon arrival at CHAS. Samples were: Preserved (U) Unpreserved

Sample I.D.	Sampling Information			Analysis										# of con.	Comments (Special instructions, cautions, etc.)	CHAS Sample #
	Date	Time	Station Location	Sample Type	PCB											
ADJUSTED - 1/3/92	1/3/92		OUTSIDE TRANSFER WALL	WPC	X									1	20CCT X 20CCT	010
ADJUSTED - 1/4/92	1/4/92				X									1		020
ADJUSTED - 1/4/92	1/4/92				X									1		030
ADJUSTED - 1/4/92	1/4/92				X									1		040
ADJUSTED - 1/4/92	1/4/92				X									1		050
ADJUSTED - 1/4/92	1/4/92				X									1		060
ADJUSTED - 1/4/92	1/4/92				X									1		070
ADJUSTED - 1/4/92	1/4/92				X									1		080

Received by: John M. Spencer Date: 1/15/92 Time: 1:15 pm

Standard laboratory turnaround time is 2 weeks from date of receipt. Accelerated turnaround may be assessed surcharge. Accelerated turnaround requested: _____

Turnaround: 24 hrs 48 hrs 1 week 2 weeks other: _____